



COMPUTERS

Fault Report

Date: 12 August 2024

Technician	Client	Ticket No
Kagisho	Blackhound Enterprises (Pty) Ltd -	526505

Item Description:
Geforce Dual-RTX3060TI-8GB-MINI-V2
Item Details:
Grpahics card 8GB - Dual fan , Serial Number - M8YVNC02S213F8L
Diagnostics Outcome:
GPU fan makes a grinding noise when on Had GPU on GPU Stress test the fans were constantly out of alignment causing the GPU to move as well as overheat Fan is faulty which causes it to not turn properly which causes the GPU to overheat causing other problems possible cause Accidental damage. would recommend replacing the GPU
Cause of Damage:
Possible Cause: Accidental Damage
Repair Status:
Not Economically viable to repair - Please refer replacement quotation

Thank you for your business!

309 Cape Road • Newton Park, Port Elizabeth • 041 363 5110